

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_160219\_02 LOKASI : AIR RUMBAI

KECAMATAN: PANGKALAN LAPAM
KABUPATEN: OGAN KOMERING ILIR
PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SABTU, 02 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:10:02	0.37	0.37	0.37	68.03	68	68.1	0	0	0	AMAN
05:20:03	0.37	0.37	0.37	67.8	67.8	67.8	0	0	0	AMAN
07:40:04	0.38	0.37	0.38	67.95	67.9	68	6.2	1	5.2	AMAN
08:00:03	0.38	0.37	0.38	67.93	67.9	68	1	0.2	0.4	AMAN
12:20:00	0.37	0.37	0.37	68.1	68.1	68.1	0	0	0	AMAN
14:10:01	0.37	0.36	0.37	67.74	67.7	67.8	0	0	0	AMAN
16:40:02	0.37	0.37	0.37	67.8	67.8	67.8	0	0	0	AMAN
17:30:03	0.37	0.37	0.37	67.75	67.7	67.8	0	0	0	AMAN
18:10:03	0.37	0.37	0.37	67.73	67.7	67.8	0	0	0	AMAN
19:00:02	0.37	0.37	0.37	67.85	67.8	67.9	0	0	0	AMAN
20:00:03	0.37	0.37	0.37	67.83	67.7	67.9	0	0	0	AMAN
21:10:02	0.37	0.36	0.37	67.85	67.7	67.9	0	0	0	AMAN
22:00:04	0.37	0.36	0.37	67.7	67.6	67.8	0	0	0	AMAN
23:00:01	0.37	0.37	0.37	67.7	67.7	67.7	0	0	0	AMAN

http://sipalaga.brg.go.id