

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : LUMPUR1 LOKASI : AS1R-RIDING

KECAMATAN: PANGKALAN LAPAM
KABUPATEN: OGAN KOMERING ILIR
PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SELASA, 12 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	-3.23	-3.23	-3.23	8.95	8.95	8.95	0	0	0	BAHAYA
01:00:00	-3.23	-3.23	-3.23	8.95	8.95	8.95	5	0	3.5	BAHAYA
02:00:00	-3.23	-3.23	-3.23	8.95	8.95	8.95	7.5	0.5	3.5	BAHAYA
03:00:00	-3.23	-3.23	-3.23	8.95	8.95	8.95	3	0	1.5	BAHAYA
04:00:00	-3.23	-3.23	-3.23	8.95	8.95	8.95	2.5	0	0.5	BAHAYA
05:00:00	-3.23	-3.23	-3.23	8.95	8.95	8.95	0	0	0	BAHAYA
06:00:00	-3.23	-3.23	-3.23	8.93	8.88	9.01	0	0	0	BAHAYA
07:00:00	-3.23	-3.23	-3.23	8.69	8.61	8.74	0	0	0	BAHAYA
08:00:00	-3.23	-3.23	-3.23	8.59	8.54	8.61	0	0	0	BAHAYA
09:00:00	-3.23	-3.23	-3.23	8.63	8.61	8.68	0	0	0	BAHAYA
10:00:00	-3.23	-3.23	-3.23	8.71	8.68	8.74	0	0	0	BAHAYA
11:00:00	-3.23	-3.23	-3.23	8.74	8.74	8.74	0	0	0	BAHAYA

http://sipalaga.brg.go.id