

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_140412\_02 LOKASI : SUNGAI GAUNG 2

**KECAMATAN: GAUNG** 

**KABUPATEN: INDRAGIRI HILIR** 

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI RABU, 27 FEBRUARI 2019

| Jam      | Ground Water Level (meter) |       |       | Soil Moisture (°/ <sub>o</sub> ) |      |      | Curah Hujan (mm) |     |     | Ctatus |
|----------|----------------------------|-------|-------|----------------------------------|------|------|------------------|-----|-----|--------|
|          | Rataan                     | Min   | Max   | Rataan                           | Min  | Max  | Komposit         | Min | Max | Status |
| 06:40:01 | -0.39                      | -0.39 | -0.39 | 46.7                             | 46.7 | 46.7 | 0                | 0   | 0   | SIAGA  |
| 09:30:03 | -0.4                       | -0.4  | -0.4  | 47                               | 47   | 47   | 0                | 0   | 0   | SIAGA  |
| 11:50:00 | -0.4                       | -0.4  | -0.4  | 47                               | 47   | 47   | 0                | 0   | 0   | SIAGA  |
| 16:00:00 | -0.4                       | -0.4  | -0.4  | 46.5                             | 46.5 | 46.5 | 0                | 0   | 0   | SIAGA  |
| 20:00:02 | -0.35                      | -0.38 | -0.33 | 47.85                            | 46.6 | 49.1 | 3.6              | 1   | 2.6 | SIAGA  |

http://sipalaga.brg.go.id