

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG2

LOKASI : PULAI GADING
KECAMATAN : BAYUNG LENCIR
KABUPATEN : MUSI BANYUASIN
PROVINSI : SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 21 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.16	0.16	0.17	101.53	101.35	101.62	0	0	0	AMAN
01:00:00	0.16	0.16	0.17	101.81	101.75	101.88	0	0	0	AMAN
02:00:00	0.16	0.16	0.17	101.88	101.82	101.95	0	0	0	AMAN
03:00:00	0.16	0.16	0.16	101.94	101.88	101.95	0	0	0	AMAN
04:00:00	0.16	0.16	0.16	101.97	101.95	102.02	0	0	0	AMAN
05:00:00	0.16	0.16	0.16	102.01	101.95	102.02	0	0	0	AMAN
06:00:00	0.16	0.16	0.16	102	101.95	102.09	0	0	0	AMAN
07:00:00	0.16	0.16	0.16	102.37	101.88	102.56	0	0	0	AMAN
08:00:00	0.16	0.16	0.16	102.46	102.29	102.56	0	0	0	AMAN
09:00:00	0.16	0.16	0.16	102.14	101.88	102.29	0	0	0	AMAN
10:00:00	0.16	0.16	0.17	101.26	101.15	101.68	0	0	0	AMAN
11:00:00	0.17	0.17	0.17	100.84	100.62	101.15	0	0	0	AMAN
12:00:00	0.17	0.17	0.17	101.17	101.15	101.22	0	0	0	AMAN

http://sipalaga.brg.go.id