

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : LUMPUR2

LOKASI: PS1-SEBOKOR, PADANG SUGIHAN

**KECAMATAN: AIR SUGIHAN** 

KABUPATEN: OGAN KOMERING ILIR PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI JUMAT, 15 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.03	0.03	0.04	132.68	132.21	133.32	0	0	0	AMAN
01:00:00	0.04	0.04	0.04	132.91	132.33	133.57	0	0	0	AMAN
02:00:00	0.04	0.03	0.04	132.73	132.21	133.32	0	0	0	AMAN
03:00:00	0.03	0.03	0.03	133.08	132.21	133.83	0	0	0	AMAN
04:00:00	0.03	0.03	0.03	133.01	132.7	133.45	0	0	0	AMAN
05:00:00	0.03	0.03	0.03	132.6	131.97	133.45	0	0	0	AMAN
06:00:00	0.03	0.03	0.03	133.2	132.95	133.45	0	0	0	AMAN
07:00:00	0.03	0.03	0.03	132.95	132.46	133.7	0	0	0	AMAN
08:00:00	0.03	0.03	0.03	133.12	132.83	133.45	0	0	0	AMAN
09:00:00	0.03	0.03	0.03	132.97	132.58	133.57	0	0	0	AMAN
10:00:00	0.03	0.03	0.03	132.7	132.58	132.83	0	0	0	AMAN

http://sipalaga.brg.go.id