

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG2

LOKASI : PULAI GADING
KECAMATAN : BAYUNG LENCIR
KABUPATEN : MUSI BANYUASIN
PROVINSI : SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SENIN, 25 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.12	0.12	0.13	102.37	102.22	102.5	0	0	0	AMAN
01:00:00	0.13	0.13	0.13	102.64	102.56	102.7	0	0	0	AMAN
02:00:00	0.13	0.13	0.13	102.77	102.77	102.77	0	0	0	AMAN
03:00:00	0.13	0.13	0.13	102.82	102.77	102.84	0	0	0	AMAN
04:00:00	0.13	0.13	0.13	102.92	102.91	102.98	0	0	0	AMAN
05:00:00	0.12	0.12	0.13	102.91	102.91	102.91	0	0	0	AMAN
06:00:00	0.12	0.12	0.12	102.93	102.91	102.98	0	0	0	AMAN
07:00:00	0.12	0.12	0.12	102.85	102.7	102.91	0	0	0	AMAN
08:00:00	0.12	0.12	0.12	102.73	102.63	102.77	0	0	0	AMAN
09:00:00	0.12	0.12	0.13	102.36	102.22	102.5	0	0	0	AMAN
10:00:00	0.13	0.13	0.13	102.02	101.68	102.22	0	0	0	AMAN
11:00:00	0.13	0.13	0.14	101.27	101.15	101.48	0	0	0	AMAN

http://sipalaga.brg.go.id