

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_611203_02 LOKASI : SIMPANG KANAN 2 KECAMATAN : SUNGAI AMBAWANG

KABUPATEN: KUBU RAYA

PROVINSI: KALIMANTAN BARAT

DATA TABEL: JAM-JAMAN PADA HARI MINGGU, 24 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Otatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:02	-0.5	-0.5	-0.49	7.47	7.3	7.6	0.4	0	0.2	ВАНАҮА
01:10:02	-0.49	-0.5	-0.49	7.72	7.6	7.9	0.2	0	0.2	ВАНАҮА
02:10:00	-0.5	-0.5	-0.5	8.05	7.9	8.2	0	0	0	ВАНАҮА
03:10:17	-0.5	-0.51	-0.5	7.9	7.9	7.9	0	0	0	ВАНАҮА
04:50:06	-0.5	-0.5	-0.5	8.2	8.2	8.2	0	0	0	ВАНАҮА
05:20:15	-0.5	-0.5	-0.5	8	8	8	0	0	0	ВАНАҮА
06:50:01	-0.5	-0.5	-0.5	8	8	8	0	0	0	ВАНАҮА
07:00:01	-0.51	-0.52	-0.5	8	8	8	0	0	0	ВАНАҮА
08:00:33	-0.5	-0.5	-0.5	8.15	8	8.3	0	0	0	ВАНАҮА
09:00:14	-0.5	-0.51	-0.5	8.2	8.1	8.3	0	0	0	ВАНАҮА
11:30:23	-0.5	-0.5	-0.5	8.4	8.4	8.4	0	0	0	ВАНАҮА
12:50:53	-0.5	-0.5	-0.5	8.5	8.5	8.5	0	0	0	ВАНАҮА
13:10:42	-0.5	-0.5	-0.5	8.35	8.2	8.5	0	0	0	ВАНАҮА
14:30:16	-0.5	-0.5	-0.5	8.5	8.5	8.5	0	0	0	ВАНАҮА
15:00:10	-0.5	-0.5	-0.5	8.6	8.6	8.6	0	0	0	ВАНАҮА
16:40:10	-0.5	-0.5	-0.5	8.6	8.5	8.7	4.6	1.2	3.4	ВАНАҮА
17:00:53	-0.5	-0.5	-0.5	8.8	8.8	8.8	0.4	0.4	0.4	ВАНАҮА
18:10:53	-0.51	-0.51	-0.5	9.05	8.9	9.2	0.6	0.2	0.4	ВАНАҮА
19:10:19	-0.51	-0.51	-0.5	9.08	8.7	9.2	1	0.2	0.4	ВАНАҮА
20:30:01	-0.5	-0.5	-0.5	8.8	8.8	8.8	0	0	0	ВАНАҮА
21:00:34	-0.51	-0.51	-0.5	8.6	8.5	8.7	0	0	0	ВАНАҮА
22:50:45	-0.5	-0.5	-0.5	8.2	8.2	8.2	0	0	0	ВАНАҮА

http://sipalaga.brg.go.id