

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG2

LOKASI : PULAI GADING
KECAMATAN : BAYUNG LENCIR
KABUPATEN : MUSI BANYUASIN
PROVINSI : SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

| Jam      | Ground Water Level (meter) |      |      | Soil Moisture (°/ <sub>o</sub> ) |        |        | Curah Hujan (mm) |     |     | Ctatus |
|----------|----------------------------|------|------|----------------------------------|--------|--------|------------------|-----|-----|--------|
|          | Rataan                     | Min  | Max  | Rataan                           | Min    | Max    | Komposit         | Min | Max | Status |
| 00:00:00 | 0.17                       | 0.18 | 0.18 | 100.49                           | 100.43 | 100.56 | 0                | 0   | 0   | AMAN   |
| 01:00:00 | 0.17                       | 0.18 | 0.18 | 100.46                           | 100.43 | 100.49 | 0                | 0   | 0   | AMAN   |
| 02:00:00 | 0.17                       | 0.18 | 0.18 | 100.41                           | 100.36 | 100.49 | 0                | 0   | 0   | AMAN   |
| 03:00:00 | 0.17                       | 0.18 | 0.18 | 100.4                            | 100.36 | 100.43 | 0                | 0   | 0   | AMAN   |
| 04:00:00 | 0.17                       | 0.18 | 0.18 | 100.58                           | 100.43 | 100.62 | 0                | 0   | 0   | AMAN   |
| 05:00:00 | 0.18                       | 0.18 | 0.18 | 100.62                           | 100.62 | 100.62 | 0                | 0   | 0   | AMAN   |

http://sipalaga.brg.go.id