

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_140412_02 LOKASI : SUNGAI GAUNG 2

KECAMATAN: GAUNG

KABUPATEN: INDRAGIRI HILIR

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI SENIN, 11 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
02:30:00	-0.56	-0.56	-0.56	39.4	39.4	39.4	0	0	0	BAHAYA
07:00:03	-0.56	-0.56	-0.56	39.65	39.6	39.7	0	0	0	BAHAYA
08:50:01	-0.56	-0.56	-0.56	39.7	39.7	39.7	0	0	0	BAHAYA
18:10:01	-0.56	-0.56	-0.56	38.8	38.8	38.8	0	0	0	BAHAYA
19:00:02	-0.57	-0.57	-0.57	38.8	38.8	38.8	1.2	0.6	0.6	BAHAYA
20:00:02	-0.56	-0.56	-0.56	38.5	38.5	38.5	0	0	0	BAHAYA
21:00:01	-0.57	-0.57	-0.57	38.9	38.9	38.9	0	0	0	BAHAYA
22:20:03	-0.57	-0.57	-0.57	38.6	38.6	38.6	0	0	0	BAHAYA
23:20:02	-0.57	-0.57	-0.57	38.9	38.9	38.9	0	0	0	BAHAYA

http://sipalaga.brg.go.id