

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_627104\_03 LOKASI : TN SEBANGAU 3

**KECAMATAN: SABANGAU** 

KABUPATEN: KOTA PALANGKARAYA PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI SABTU, 23 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Sialus
09:00:02	0.8	0.8	0.81	84.8	84.8	84.8	0	0	0	AMAN
14:00:02	0.79	0.79	0.79	84.4	84.4	84.4	0	0	0	AMAN
15:20:03	0.78	0.78	0.78	84.4	84.4	84.4	0	0	0	AMAN
16:30:01	0.78	0.78	0.78	84.4	84.4	84.4	0	0	0	AMAN
18:40:02	0.77	0.77	0.77	84.4	84.4	84.4	0	0	0	AMAN

http://sipalaga.brg.go.id