

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : MUBA2 LOKASI : KEPAYANG

KECAMATAN: BAYUNG LENCIR
KABUPATEN: MUSI BANYUASIN
PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SELASA, 12 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	-4.54	-4.54	-4.54	15.16	15.11	15.22	0	0	0	BAHAYA
01:00:00	-4.54	-4.54	-4.54	15.11	15.11	15.11	0	0	0	BAHAYA
02:00:00	-4.53	-4.53	-4.54	15.08	14.89	15.38	0	0	0	BAHAYA
03:00:00	-4.54	-4.54	-4.54	14.94	14.89	15	0	0	0	BAHAYA
04:00:00	-4.53	-4.53	-4.54	15.03	14.94	15.11	0	0	0	BAHAYA
05:00:00	-4.53	-4.53	-4.53	15.23	15.11	15.33	0.5	0	0.5	BAHAYA
06:00:00	-4.53	-4.53	-4.53	15.31	15.22	15.38	0	0	0	BAHAYA
07:00:00	-4.54	-4.53	-4.54	14.87	14.5	15.16	0	0	0	BAHAYA
08:00:00	-4.54	-4.54	-4.55	14.21	14.05	14.39	0	0	0	BAHAYA
09:00:00	-4.55	-4.55	-4.55	13.76	13.65	13.94	0	0	0	BAHAYA
10:00:00	-4.55	-4.55	-4.55	13.64	13.59	13.71	0	0	0	BAHAYA
11:00:00	-4.55	-4.55	-4.55	13.53	13.53	13.53	0	0	0	BAHAYA

http://sipalaga.brg.go.id