

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : MUBA2 LOKASI : KEPAYANG KECAMATAN : BAYUNG LENCIR

KECAMATAN: BAYUNG LENCIR
KABUPATEN: MUSI BANYUASIN
PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI MINGGU, 24 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatua
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	-4.45	-4.44	-4.45	40.05	38.08	41.35	0	0	0	BAHAYA
01:00:00	-4.46	-4.44	-4.47	40.34	38.69	43.11	0	0	0	BAHAYA
02:00:00	-4.45	-4.44	-4.47	41.71	40.05	44.53	0	0	0	BAHAYA
03:00:00	-4.45	-4.43	-4.47	42.82	40.28	45.79	0	0	0	BAHAYA
04:00:00	-4.45	-4.44	-4.46	42.71	40.83	44	5	0	5	BAHAYA
05:00:00	-4.45	-4.45	-4.47	41.9	40.54	43.48	5	0	3	BAHAYA
06:00:00	-4.46	-4.46	-4.47	41.24	40.67	42.1	4.5	0.5	1	BAHAYA
07:00:00	-4.06	-4.45	-2.04	50.86	41.29	93.88	5	0.5	1	BAHAYA
08:00:00	-4.46	-4.44	-4.47	44.14	42.13	46.1	1.5	0	0.5	BAHAYA
09:00:00	-4.49	-4.48	-4.5	42.15	41.35	42.85	0.5	0	0.5	BAHAYA
10:00:00	-4.49	-4.49	-4.5	41.63	40.9	41.97	0	0	0	BAHAYA
11:00:00	-4.49	-4.49	-4.5	41.14	40.21	42.79	0	0	0	BAHAYA
12:00:00	-4.49	-4.48	-4.5	40.08	38.76	41.19	0	0	0	BAHAYA
13:00:00	-4.49	-4.49	-4.49	40.05	40.05	40.05	0	0	0	BAHAYA

http://sipalaga.brg.go.id