

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : MUBA2 LOKASI : KEPAYANG

KECAMATAN: BAYUNG LENCIR
KABUPATEN: MUSI BANYUASIN
PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SENIN, 04 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	-4.54	-4.54	-4.54	15.24	15.11	15.38	0	0	0	BAHAYA
01:00:00	-4.54	-4.54	-4.54	15.28	15.22	15.33	0	0	0	BAHAYA
02:00:00	-4.54	-4.53	-4.54	15.3	15.22	15.38	0	0	0	BAHAYA
03:00:00	-4.54	-4.54	-4.54	15.33	15.27	15.38	0	0	0	BAHAYA
04:00:00	-4.54	-4.54	-4.54	15.31	15.27	15.38	0	0	0	BAHAYA
05:00:00	-4.54	-4.54	-4.54	15.24	15.22	15.27	0	0	0	BAHAYA
06:00:00	-4.54	-4.54	-4.54	15.18	14.89	15.27	0	0	0	BAHAYA
07:00:00	-4.54	-4.54	-4.55	14.39	13.99	14.89	0	0	0	BAHAYA
08:00:00	-4.55	-4.55	-4.55	13.74	13.65	13.88	0	0	0	BAHAYA
09:00:00	-4.55	-4.55	-4.55	13.53	13.48	13.59	0	0	0	BAHAYA

http://sipalaga.brg.go.id