

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_140701_01

LOKASI : SEI SEGAJAH MAKMUR

KECAMATAN: KUBU

KABUPATEN: ROKAN HILIR

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			- Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:03	-0.74	-0.74	-0.73	12.2	12.1	12.3	0	0	0	BAHAYA
01:00:00	-0.74	-0.74	-0.74	12.37	12.2	12.4	0	0	0	BAHAYA
02:00:00	-0.74	-0.74	-0.74	12.32	12.2	12.4	0	0	0	BAHAYA
03:00:02	-0.74	-0.74	-0.74	12.3	12.3	12.3	0	0	0	BAHAYA
05:00:02	-0.74	-0.74	-0.74	12.3	12.3	12.3	0	0	0	BAHAYA
11:30:01	-0.74	-0.75	-0.74	12.03	12	12.1	0	0	0	BAHAYA
12:00:02	-0.74	-0.75	-0.74	12.17	12	12.3	0	0	0	ВАНАҮА
13:00:01	-0.74	-0.74	-0.74	12.37	12.2	12.4	0	0	0	BAHAYA
14:00:01	-0.75	-0.75	-0.74	12.42	12.1	12.5	0	0	0	BAHAYA
15:00:02	-0.75	-0.75	-0.74	12.33	12.1	12.5	0	0	0	BAHAYA
16:00:01	-0.75	-0.75	-0.74	12.33	12.1	12.5	0	0	0	BAHAYA
17:00:02	-0.75	-0.75	-0.74	12.3	12.3	12.3	0	0	0	BAHAYA
18:00:00	-0.75	-0.75	-0.75	12.3	12.3	12.3	0	0	0	BAHAYA
19:00:01	-0.75	-0.75	-0.75	12.3	12.3	12.3	0	0	0	BAHAYA
20:00:02	-0.75	-0.75	-0.75	12.3	12.3	12.3	0	0	0	BAHAYA
21:00:02	-0.75	-0.75	-0.75	12.23	12.2	12.3	0	0	0	ВАНАҮА
22:00:01	-0.75	-0.75	-0.74	12.2	12.2	12.2	0	0	0	ВАНАҮА
23:00:02	-0.75	-0.75	-0.74	12.27	12.2	12.4	0	0	0	ВАНАҮА

http://sipalaga.brg.go.id