

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_160214_03

LOKASI : PADANG SUGIHAN 3 (SM)

KECAMATAN: AIR SUGIHAN

KABUPATEN: OGAN KOMERING ILIR PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:02	0.51	0.48	0.51	57.05	56.9	57.2	0	0	0	AMAN
01:00:04	0.51	0.51	0.52	57.2	57.2	57.2	0	0	0	AMAN
02:00:00	0.51	0.51	0.52	57.47	56.9	57.7	1.4	0	1.4	AMAN
03:00:00	0.51	0.51	0.51	57.63	57.4	57.7	0.4	0	0.4	AMAN
11:30:03	0.52	0.52	0.52	56.87	56.8	56.9	0	0	0	AMAN
12:00:16	0.51	0.51	0.52	56.94	56.8	57.2	0	0	0	AMAN
13:00:29	0.54	0.53	0.55	57.4	57.4	57.4	8.8	0	4.6	AMAN
14:00:14	0.56	0.56	0.57	57.4	57.4	57.4	9.2	0.6	4.8	AMAN
15:00:12	0.58	0.57	0.58	57.4	57.4	57.4	4.4	0	4	AMAN
16:00:00	0.58	0.58	0.59	57.4	57.4	57.4	20.4	0	20.4	AMAN
17:00:06	0.59	0.59	0.6	57.4	57.4	57.4	0	0	0	AMAN
18:10:10	0.6	0.6	0.6	57.9	57.9	57.9	0	0	0	AMAN
19:10:09	0.6	0.6	0.6	57.9	57.9	57.9	9.2	0	9.2	AMAN
20:00:29	0.6	0.6	0.6	57.9	57.9	57.9	0	0	0	AMAN
21:10:57	0.61	0.61	0.61	57.9	57.9	57.9	0	0	0	AMAN
22:00:01	0.61	0.61	0.62	57.9	57.9	57.9	0	0	0	AMAN
23:00:19	0.62	0.62	0.62	57.9	57.9	57.9	0	0	0	AMAN

http://sipalaga.brg.go.id