

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG2

LOKASI : PULAI GADING
KECAMATAN : BAYUNG LENCIR
KABUPATEN : MUSI BANYUASIN
PROVINSI : SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI MINGGU, 03 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			01-1
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.17	0.17	0.18	102.31	102.22	102.43	0	0	0	AMAN
01:00:00	0.17	0.18	0.18	102.55	102.5	102.63	0	0	0	AMAN
02:00:00	0.17	0.18	0.18	102.7	102.63	102.77	0	0	0	AMAN
03:00:00	0.17	0.18	0.18	103	102.77	103.11	0	0	0	AMAN
04:00:00	0.17	0.17	0.18	102.76	102.7	102.77	0	0	0	AMAN
05:00:00	0.17	0.17	0.18	102.75	102.7	102.77	0	0	0	AMAN
06:00:00	0.17	0.17	0.17	102.62	102.56	102.7	0	0	0	AMAN
07:00:00	0.17	0.17	0.17	102.65	102.63	102.7	0	0	0	AMAN
08:00:00	0.17	0.17	0.17	102.56	102.43	102.63	0	0	0	AMAN
09:00:00	0.17	0.17	0.17	102.26	102.16	102.36	0	0	0	AMAN
10:00:00	0.17	0.17	0.18	101.69	101.28	102.02	0	0	0	AMAN
11:00:00	0.18	0.18	0.18	101.15	101.15	101.15	0	0	0	AMAN

http://sipalaga.brg.go.id