

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : KALBAR1 LOKASI : KALBAR

KECAMATAN : SUNGAI RAYA KABUPATEN : KUBU RAYA

PROVINSI: KALIMANTAN BARAT

DATA TABEL: JAM-JAMAN PADA HARI SELASA, 05 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			01-1
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	-0.53	-0.54	-0.53	-3.9	-3.9	-3.9	0	0	0	BAHAYA
01:00:00	-0.54	-0.54	-0.54	-3.9	-3.9	-3.9	0	0	0	BAHAYA
02:00:00	-0.54	-0.54	-0.54	-3.9	-3.9	-3.9	0	0	0	BAHAYA
03:00:00	-0.54	-0.54	-0.54	-3.9	-3.9	-3.9	0	0	0	BAHAYA
04:00:00	-0.54	-0.54	-0.54	-3.9	-3.9	-3.9	0	0	0	BAHAYA
05:00:00	-0.54	-0.54	-0.54	-3.9	-3.9	-3.9	0	0	0	BAHAYA
06:00:00	-0.54	-0.54	-0.54	-3.9	-3.9	-3.9	0	0	0	BAHAYA
07:00:00	-0.54	-0.54	-0.54	-3.9	-3.9	-3.9	0	0	0	BAHAYA
08:00:00	-0.54	-0.54	-0.54	-3.9	-3.9	-3.9	0	0	0	BAHAYA
09:00:00	-0.54	-0.54	-0.54	-3.9	-3.9	-3.9	0	0	0	BAHAYA
10:00:00	-0.54	-0.54	-0.54	-3.9	-3.9	-3.9	0	0	0	BAHAYA
11:00:00	-0.54	-0.54	-0.54	-3.9	-3.9	-3.9	0	0	0	ВАНАҮА

http://sipalaga.brg.go.id