

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_140802\_02 LOKASI : PENYENGAT 2 KECAMATAN : SUNGAI APIT

KABUPATEN : SIAK PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:02	-0.61	-0.61	-0.61	7.87	7.8	7.9	0	0	0	BAHAYA
01:00:04	-0.61	-0.62	-0.61	7.9	7.9	7.9	0	0	0	BAHAYA
02:00:00	-0.61	-0.62	-0.61	7.9	7.8	8	0	0	0	BAHAYA
03:00:01	-0.61	-0.61	-0.61	7.96	7.8	8	0	0	0	BAHAYA
05:00:01	-0.61	-0.61	-0.61	8.1	8.1	8.1	0	0	0	BAHAYA
11:30:01	-0.62	-0.62	-0.62	7.83	7.7	8	0	0	0	BAHAYA
12:00:01	-0.62	-0.63	-0.62	7.92	7.8	8	0	0	0	BAHAYA
13:00:01	-0.62	-0.62	-0.62	7.98	7.9	8	0	0	0	BAHAYA
14:00:03	-0.62	-0.62	-0.62	7.9	7.7	8	0	0	0	BAHAYA
15:00:02	-0.62	-0.63	-0.62	7.88	7.8	8	0	0	0	BAHAYA
16:10:01	-0.62	-0.62	-0.62	7.84	7.8	7.9	0	0	0	BAHAYA
17:00:02	-0.62	-0.62	-0.62	7.98	7.9	8	0	0	0	BAHAYA
18:00:02	-0.62	-0.63	-0.62	7.9	7.9	7.9	0	0	0	BAHAYA
19:00:02	-0.62	-0.63	-0.62	7.9	7.9	7.9	0	0	0	BAHAYA
20:00:02	-0.62	-0.63	-0.62	7.9	7.9	7.9	0	0	0	BAHAYA
21:00:02	-0.62	-0.63	-0.62	7.9	7.9	7.9	0	0	0	BAHAYA
22:00:03	-0.62	-0.63	-0.62	7.87	7.7	7.9	0	0	0	BAHAYA
23:00:03	-0.62	-0.63	-0.62	7.77	7.7	7.9	0	0	0	BAHAYA

http://sipalaga.brg.go.id