

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_160219_02 LOKASI : AIR RUMBAI

KECAMATAN: PANGKALAN LAPAM
KABUPATEN: OGAN KOMERING ILIR
PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 21 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
02:00:02	0.38	0.38	0.38	67.25	67.2	67.3	0	0	0	AMAN
03:00:03	0.38	0.38	0.38	67.3	67.3	67.3	0	0	0	AMAN
05:50:03	0.38	0.38	0.38	67.2	67.2	67.2	0	0	0	AMAN
06:00:00	0.38	0.38	0.38	67.3	67.3	67.3	0	0	0	AMAN
09:00:03	0.38	0.38	0.38	67.25	67.2	67.3	0	0	0	AMAN
10:10:03	0.38	0.38	0.38	67.2	67.1	67.3	0	0	0	AMAN
11:00:03	0.38	0.38	0.38	67.3	67.3	67.3	0	0	0	AMAN
12:10:02	0.38	0.38	0.38	67.33	67.3	67.4	0	0	0	AMAN
13:10:02	0.38	0.38	0.38	67.1	67.1	67.1	0	0	0	AMAN
14:00:04	0.38	0.37	0.38	67.84	67.6	67.9	0	0	0	AMAN
15:00:04	0.38	0.38	0.38	67.9	67.9	67.9	0	0	0	AMAN
16:10:03	0.38	0.37	0.38	67.6	67.6	67.6	0	0	0	AMAN
17:00:01	0.38	0.37	0.38	67.68	67.6	67.7	0.2	0	0.2	AMAN
18:00:00	0.38	0.37	0.38	68.2	68.2	68.2	0	0	0	AMAN
19:00:00	0.37	0.37	0.38	68.2	68.2	68.2	0	0	0	AMAN
20:10:01	0.38	0.38	0.38	68.2	68.2	68.2	0	0	0	AMAN
23:30:00	0.38	0.38	0.38	68.2	68.2	68.2	0	0	0	AMAN

http://sipalaga.brg.go.id