

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : LUMPUR2

LOKASI: PS1-SEBOKOR, PADANG SUGIHAN

**KECAMATAN: AIR SUGIHAN** 

KABUPATEN: OGAN KOMERING ILIR PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 14 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Ctatua
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.04	0.04	0.04	133.28	132.58	133.95	0	0	0	AMAN
01:00:00	0.04	0.04	0.04	133.28	132.33	133.95	0	0	0	AMAN
02:00:00	0.04	0.04	0.04	133.81	133.2	134.58	0	0	0	AMAN
03:00:00	0.04	0.04	0.04	134.12	133.7	134.71	0	0	0	AMAN
04:00:00	0.04	0.04	0.04	133.78	133.32	134.46	0	0	0	AMAN
05:00:00	0.04	0.04	0.04	134.51	133.32	136	0	0	0	AMAN
06:00:00	0.04	0.04	0.04	133.71	132.21	134.46	0	0	0	AMAN
07:00:00	0.04	0.04	0.04	134.42	133.83	134.71	0	0	0	AMAN
08:00:00	0.04	0.04	0.04	134.31	133.83	135.35	0	0	0	AMAN
09:00:00	0.04	0.04	0.04	134.54	134.33	134.71	0	0	0	AMAN
10:00:00	0.04	0.04	0.04	134.12	132.7	134.84	0	0	0	AMAN
11:00:00	0.04	0.04	0.04	133.96	132.7	135.35	0	0	0	AMAN
12:00:00	0.04	0.04	0.04	133.83	133.83	133.83	0	0	0	AMAN

http://sipalaga.brg.go.id