

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : LUMPUR2

LOKASI: PS1-SEBOKOR, PADANG SUGIHAN

KECAMATAN: AIR SUGIHAN

KABUPATEN: OGAN KOMERING ILIR PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SENIN, 04 MARET 2019

| Jam | Ground Water Level (meter) | | | Soil Moisture (°/ _o) | | | Curah Hujan (mm) | | | Ctatus |
|----------|----------------------------|------|------|----------------------------------|--------|--------|------------------|-----|-----|--------|
| | Rataan | Min | Max | Rataan | Min | Max | Komposit | Min | Max | Status |
| 00:00:00 | 0.06 | 0.06 | 0.07 | 129.59 | 129.22 | 129.92 | 0 | 0 | 0 | AMAN |
| 01:00:00 | 0.07 | 0.07 | 0.07 | 129.43 | 129.1 | 129.81 | 0 | 0 | 0 | AMAN |
| 02:00:00 | 0.07 | 0.07 | 0.07 | 129.55 | 128.99 | 130.04 | 0 | 0 | 0 | AMAN |
| 03:00:00 | 0.07 | 0.07 | 0.07 | 129.47 | 129.1 | 129.81 | 0 | 0 | 0 | AMAN |
| 04:00:00 | 0.07 | 0.07 | 0.07 | 129.73 | 129.34 | 130.16 | 0 | 0 | 0 | AMAN |
| 05:00:00 | 0.06 | 0.06 | 0.06 | 128.12 | 127.72 | 128.52 | 0 | 0 | 0 | AMAN |
| 06:00:00 | 0.06 | 0.06 | 0.06 | 127.28 | 127.04 | 127.6 | 0 | 0 | 0 | AMAN |
| 07:00:00 | 0.06 | 0.06 | 0.06 | 126.96 | 126.59 | 127.26 | 0 | 0 | 0 | AMAN |
| 08:00:00 | 0.06 | 0.06 | 0.06 | 126.89 | 126.48 | 127.15 | 0 | 0 | 0 | AMAN |
| 09:00:00 | 0.06 | 0.06 | 0.06 | 127.09 | 126.81 | 127.26 | 0 | 0 | 0 | AMAN |
| 10:00:00 | 0.07 | 0.07 | 0.07 | 127.23 | 127.04 | 127.38 | 0 | 0 | 0 | AMAN |
| 11:00:00 | 0.07 | 0.07 | 0.07 | 127.32 | 127.15 | 127.49 | 0 | 0 | 0 | AMAN |
| 12:00:00 | 0.07 | 0.07 | 0.07 | 127.49 | 127.26 | 127.83 | 0 | 0 | 0 | AMAN |
| 13:00:00 | 0.07 | 0.07 | 0.07 | 127.86 | 127.72 | 127.95 | 0 | 0 | 0 | AMAN |

http://sipalaga.brg.go.id