

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_621101_02 LOKASI : DANDANG

KECAMATAN: PANDIH BATU KABUPATEN: PULANG PISAU

PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI SENIN, 25 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
06:40:05	0.15	0.15	0.15	81.4	81.4	81.4	0	0	0	AMAN
07:00:15	0.14	0.14	0.14	81.33	81.3	81.4	0	0	0	AMAN
08:20:05	0.14	0.14	0.14	81.45	81.4	81.5	0	0	0	AMAN
09:20:08	0.14	0.14	0.14	81.6	81.6	81.6	0	0	0	AMAN
10:20:38	0.14	0.14	0.14	81.4	81.4	81.4	0	0	0	AMAN
11:00:03	0.13	0.12	0.14	81.07	81	81.1	0	0	0	AMAN
12:00:23	0.14	0.14	0.14	81.1	81.1	81.1	0	0	0	AMAN
14:00:05	0.13	0.12	0.13	80.28	80.1	80.5	0	0	0	AMAN
15:50:00	0.13	0.13	0.13	80.5	80.5	80.5	0	0	0	AMAN
16:10:00	0.12	0.12	0.13	80.68	80.3	81	0.2	0	0.2	AMAN
17:10:05	0.12	0.12	0.13	80.7	80.4	80.9	0	0	0	AMAN
18:00:48	0.12	0.12	0.12	80.82	80.7	81	0	0	0	AMAN
19:20:10	0.12	0.12	0.12	81.23	81	81.3	0	0	0	AMAN
20:00:14	0.12	0.11	0.12	81.48	81.2	81.7	0	0	0	AMAN
21:00:01	0.11	0.11	0.12	81.53	81.5	81.6	0	0	0	AMAN
22:00:08	0.11	0.11	0.11	81.48	81.4	81.5	0	0	0	AMAN
23:00:01	0.11	0.11	0.11	81.4	81.4	81.4	0	0	0	AMAN

http://sipalaga.brg.go.id