

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : LUMPUR2

LOKASI: PS1-SEBOKOR, PADANG SUGIHAN

KECAMATAN: AIR SUGIHAN

KABUPATEN: OGAN KOMERING ILIR PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SABTU, 23 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.03	0.03	0.03	123.41	122.29	124.61	0	0	0	AMAN
01:00:00	0.04	0.04	0.04	122.9	121.67	123.86	0	0	0	AMAN
02:00:00	0.04	0.03	0.04	123.61	123.12	123.86	0	0	0	AMAN
03:00:00	0.04	0.04	0.04	122.58	121.87	123.02	0	0	0	AMAN
04:00:00	0.03	0.03	0.03	121.55	121.36	121.67	0	0	0	AMAN
05:00:00	0.03	0.03	0.03	121.98	121.77	122.18	0	0	0	AMAN
06:00:00	0.03	0.03	0.03	122.22	122.18	122.39	0	0	0	AMAN
07:00:00	0.03	0.03	0.03	122.37	122.18	122.49	0	0	0	AMAN
08:00:00	0.03	0.03	0.03	122.67	122.29	122.91	0	0	0	AMAN
09:00:00	0.03	0.03	0.03	122.58	122.08	122.81	0	0	0	AMAN
10:00:00	0.03	0.03	0.03	122.37	122.29	122.39	0	0	0	AMAN
11:00:00	0.03	0.03	0.03	122.67	122.39	123.02	0	0	0	AMAN
12:00:00	0.03	0.03	0.03	123.05	122.91	123.23	0	0	0	AMAN
13:00:00	0.03	0.03	0.04	123.23	123.12	123.33	0.5	0	0.5	AMAN

http://sipalaga.brg.go.id