

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_160219_02 LOKASI : AIR RUMBAI

KECAMATAN: PANGKALAN LAPAM KABUPATEN: OGAN KOMERING ILIR PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SELASA, 26 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:10:03	0.35	0.35	0.35	68.2	68.1	68.4	0	0	0	AMAN
01:00:01	0.35	0.34	0.35	68.37	68.1	68.5	0	0	0	AMAN
02:00:03	0.35	0.34	0.35	68.3	68.3	68.3	0	0	0	AMAN
05:10:02	0.35	0.35	0.35	68.3	68.3	68.3	0	0	0	AMAN
08:20:04	0.35	0.34	0.35	68.35	68.3	68.4	0	0	0	AMAN
09:00:03	0.34	0.34	0.34	68.7	68.7	68.7	0	0	0	AMAN
10:10:00	0.35	0.34	0.35	68.5	68.5	68.5	0	0	0	AMAN
11:00:03	0.34	0.34	0.35	68.7	68.7	68.7	0	0	0	AMAN
12:00:01	0.34	0.34	0.35	68.64	68.4	68.7	0	0	0	AMAN
13:00:01	0.34	0.34	0.35	68.58	68.3	68.8	0	0	0	AMAN
14:00:01	0.34	0.34	0.34	68.58	68.4	68.7	0	0	0	AMAN
15:00:03	0.34	0.34	0.34	68.5	68.4	68.6	0	0	0	AMAN
16:00:00	0.34	0.34	0.34	68.43	68.3	68.5	0.4	0	0.4	AMAN
17:00:02	0.34	0.34	0.35	68.38	68.3	68.5	0	0	0	AMAN
18:00:03	0.34	0.34	0.34	68.4	68.3	68.5	0	0	0	AMAN
19:20:03	0.34	0.34	0.34	68.4	68.4	68.4	0	0	0	AMAN
20:00:01	0.34	0.34	0.35	68.42	68.4	68.5	0	0	0	AMAN
22:10:02	0.34	0.34	0.34	68.4	68.4	68.4	0	0	0	AMAN
23:10:02	0.34	0.34	0.34	68.4	68.4	68.4	0	0	0	AMAN

http://sipalaga.brg.go.id