

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG10 LOKASI : DOMPAS KECAMATAN : BUKIT BATU KABUPATEN : BENGKALIS

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI RABU, 13 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	-1.51	-1.51	-1.51	57.07	56.01	57.76	0	0	0	BAHAYA
01:00:00	-1.51	-1.51	-1.51	55.42	55.05	55.69	0	0	0	BAHAYA
02:00:00	-1.51	-1.51	-1.51	56.75	55.55	58.09	0	0	0	BAHAYA
03:00:00	-1.51	-1.51	-1.51	61.5	59.03	63.15	0	0	0	BAHAYA
04:00:00	-1.51	-1.51	-1.51	65.36	64.37	66.23	0	0	0	BAHAYA
05:00:00	-1.51	-1.51	-1.51	66.76	66.41	67.2	0	0	0	BAHAYA
06:00:00	-1.51	-1.51	-1.51	67.76	67.35	68.1	0	0	0	BAHAYA
07:00:00	-1.51	-1.51	-1.5	70.3	67.58	71.92	0	0	0	BAHAYA
08:00:00	-1.5	-1.51	-1.5	72.72	70.15	74.46	0	0	0	BAHAYA
09:00:00	-1.6	-1.63	-1.55	75.21	74.7	75.45	0	0	0	BAHAYA
10:00:00	-1.65	-1.65	-1.63	74.76	74.18	75.33	0	0	0	BAHAYA
11:00:00	-1.65	-1.66	-1.63	73.78	73.44	74.07	0	0	0	BAHAYA
12:00:00	-1.66	-1.66	-1.64	75.1	73.52	76.05	0	0	0	BAHAYA

http://sipalaga.brg.go.id