

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : MUBA2 LOKASI : KEPAYANG KECAMATAN : BAYUNG LENCIR

KABUPATEN: MUSI BANYUASIN
PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SABTU, 23 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	-4.45	-4.44	-4.46	38.09	36.79	39.6	0	0	0	BAHAYA
01:00:00	-4.45	-4.43	-4.45	41.46	39.28	43.64	0	0	0	BAHAYA
02:00:00	-4.45	-4.43	-4.46	42.99	39.95	46.23	0	0	0	BAHAYA
03:00:00	-4.45	-4.44	-4.46	42.95	41.42	44.56	0	0	0	BAHAYA
04:00:00	-4.45	-4.44	-4.47	44.06	41.38	46.63	0	0	0	BAHAYA
05:00:00	-4.45	-4.43	-4.47	45.56	41.58	48.97	0	0	0	BAHAYA
06:00:00	-4.44	-4.43	-4.45	47.35	45.46	52.35	0	0	0	BAHAYA
07:00:00	-4.46	-4.45	-4.48	44.61	42.43	46.5	0	0	0	BAHAYA
08:00:00	-4.49	-4.48	-4.5	42.29	41.64	43.87	0	0	0	BAHAYA
09:00:00	-4.5	-4.49	-4.51	40.5	39.28	42.46	0	0	0	BAHAYA
10:00:00	-4.49	-4.49	-4.5	40.93	39.57	42.17	0	0	0	BAHAYA
11:00:00	-4.51	-4.5	-4.51	37.01	35.2	38.21	0	0	0	BAHAYA
12:00:00	-4.52	-4.51	-4.52	33.63	32.56	35.72	0	0	0	ВАНАҮА
13:00:00	-4.52	-4.52	-4.52	32.01	31.45	32.99	0	0	0	ВАНАҮА
14:00:00	-4.52	-4.52	-4.52	31.93	31.14	32.53	0	0	0	ВАНАҮА
15:00:00	-4.52	-4.52	-4.52	31.18	31.18	31.18	0	0	0	ВАНАҮА

http://sipalaga.brg.go.id