

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : LUMPUR2

LOKASI: PS1-SEBOKOR, PADANG SUGIHAN

**KECAMATAN: AIR SUGIHAN** 

KABUPATEN: OGAN KOMERING ILIR PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SABTU, 02 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.04	0.04	0.05	127.76	127.49	127.95	0	0	0	AMAN
01:00:00	0.05	0.04	0.05	127.72	127.26	128.06	0	0	0	AMAN
02:00:00	0.05	0.05	0.05	128.04	127.72	128.29	0	0	0	AMAN
03:00:00	0.05	0.05	0.05	128.12	127.72	128.87	0	0	0	AMAN
04:00:00	0.05	0.04	0.05	128.77	128.06	129.34	0	0	0	AMAN
05:00:00	0.04	0.04	0.04	128.89	128.18	129.57	0	0	0	AMAN
06:00:00	0.04	0.04	0.04	129.61	128.99	129.92	0	0	0	AMAN
07:00:00	0.05	0.04	0.05	129.2	129.1	129.45	5.5	0	2	AMAN
08:00:00	0.06	0.05	0.06	129.37	129.22	129.57	0	0	0	AMAN
09:20:00	0.06	0.06	0.06	129.61	129.45	129.81	0	0	0	AMAN
10:00:00	0.07	0.07	0.07	129.55	129.45	129.69	0	0	0	AMAN
11:00:00	0.07	0.07	0.07	129.49	129.34	129.69	0	0	0	AMAN
12:00:00	0.07	0.07	0.07	129.04	128.99	129.22	0	0	0	AMAN

http://sipalaga.brg.go.id