

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_630805_02
LOKASI : MAWAR SARI
KECAMATAN : AMUNTAI TENGAH
KABUPATEN : HULU SUNGAI UTARA
PROVINSI : KALIMANTAN SELATAN

DATA TABEL: JAM-JAMAN PADA HARI MINGGU, 24 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:10:05	-0.09	-0.09	-0.09	55.82	55.7	55.9	0	0	0	SIAGA
01:00:08	-0.09	-0.09	-0.09	55.77	55.7	55.9	0	0	0	SIAGA
02:00:08	-0.09	-0.09	-0.09	55.7	55.7	55.7	0	0	0	SIAGA
03:00:08	-0.09	-0.1	-0.09	55.72	55.7	55.8	0	0	0	SIAGA
04:00:02	-0.09	-0.1	-0.09	55.77	55.7	55.8	0	0	0	SIAGA
05:00:04	-0.09	-0.09	-0.09	55.78	55.7	55.8	0	0	0	SIAGA
06:00:00	-0.09	-0.09	-0.09	55.77	55.7	55.8	0	0	0	SIAGA
07:00:03	-0.09	-0.1	-0.09	55.92	55.7	56	0	0	0	SIAGA
08:00:02	-0.09	-0.1	-0.09	55.95	55.7	56.4	0	0	0	SIAGA
19:20:00	-0.07	-0.07	-0.07	56.1	56.1	56.1	0	0	0	SIAGA
20:00:02	-0.07	-0.07	-0.07	56.1	56.1	56.1	0	0	0	SIAGA

http://sipalaga.brg.go.id