

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG2

LOKASI : PULAI GADING
KECAMATAN : BAYUNG LENCIR
KABUPATEN : MUSI BANYUASIN
PROVINSI : SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SELASA, 26 FEBRUARI 2019

| Jam | Ground Water Level (meter) | | | Soil Moisture (°/ _o) | | | Curah Hujan (mm) | | | Ctatus |
|----------|----------------------------|------|------|----------------------------------|--------|--------|------------------|-----|-----|--------|
| | Rataan | Min | Max | Rataan | Min | Max | Komposit | Min | Max | Status |
| 00:00:00 | 0.12 | 0.12 | 0.12 | 101.58 | 101.35 | 101.82 | 0 | 0 | 0 | AMAN |
| 01:00:00 | 0.12 | 0.12 | 0.12 | 101.92 | 101.82 | 101.95 | 0 | 0 | 0 | AMAN |
| 02:00:00 | 0.12 | 0.12 | 0.12 | 102.06 | 102.02 | 102.16 | 0 | 0 | 0 | AMAN |
| 03:00:00 | 0.12 | 0.12 | 0.12 | 102.21 | 102.16 | 102.29 | 0 | 0 | 0 | AMAN |
| 04:00:00 | 0.12 | 0.12 | 0.12 | 102.29 | 102.29 | 102.29 | 0 | 0 | 0 | AMAN |
| 05:00:00 | 0.12 | 0.12 | 0.12 | 102.3 | 102.22 | 102.36 | 0 | 0 | 0 | AMAN |
| 06:00:00 | 0.12 | 0.12 | 0.12 | 102.23 | 102.22 | 102.29 | 0 | 0 | 0 | AMAN |
| 07:00:00 | 0.12 | 0.12 | 0.12 | 102.26 | 102.22 | 102.29 | 0 | 0 | 0 | AMAN |
| 08:00:00 | 0.12 | 0.12 | 0.12 | 102.05 | 101.82 | 102.22 | 0 | 0 | 0 | AMAN |
| 09:00:00 | 0.12 | 0.12 | 0.12 | 101.59 | 101.22 | 101.95 | 0 | 0 | 0 | AMAN |
| 10:00:00 | 0.12 | 0.12 | 0.12 | 101.15 | 101.08 | 101.22 | 0 | 0 | 0 | AMAN |
| 11:00:00 | 0.12 | 0.12 | 0.12 | 100.8 | 100.69 | 100.95 | 0 | 0 | 0 | AMAN |

http://sipalaga.brg.go.id