

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : LUMPUR2

LOKASI: PS1-SEBOKOR, PADANG SUGIHAN

**KECAMATAN: AIR SUGIHAN** 

KABUPATEN: OGAN KOMERING ILIR PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.03	0.03	0.03	126.44	126.14	126.93	0	0	0	AMAN
01:00:00	0.03	0.03	0.04	126.31	125.92	126.48	0	0	0	AMAN
02:00:00	0.03	0.03	0.04	126.55	126.26	127.26	0	0	0	AMAN
03:00:00	0.03	0.03	0.04	126.5	126.14	126.93	0	0	0	AMAN
04:00:00	0.03	0.03	0.03	126.83	126.48	127.38	0.5	0	0.5	AMAN
05:00:00	0.03	0.03	0.03	127.17	126.81	127.49	0	0	0	AMAN
06:00:00	0.03	0.03	0.03	126.81	126.48	127.04	0.5	0	0.5	AMAN
07:00:00	0.03	0.03	0.03	126.93	126.81	127.15	0	0	0	AMAN
08:00:00	0.03	0.03	0.03	126.78	126.48	127.26	0	0	0	AMAN
09:00:00	0.03	0.03	0.03	127.19	126.7	127.83	0	0	0	AMAN
10:00:00	0.04	0.04	0.04	127.36	126.93	127.83	0	0	0	AMAN
11:00:00	0.04	0.04	0.04	127.57	126.93	128.18	0	0	0	AMAN
12:00:00	0.04	0.04	0.04	128.23	128.06	128.75	0	0	0	AMAN

http://sipalaga.brg.go.id