

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG2

LOKASI : PULAI GADING
KECAMATAN : BAYUNG LENCIR
KABUPATEN : MUSI BANYUASIN
PROVINSI : SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SENIN, 04 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.16	0.16	0.17	103.43	103.39	103.53	0	0	0	AMAN
01:00:00	0.17	0.17	0.17	103.8	103.53	103.95	0	0	0	AMAN
02:00:00	0.17	0.17	0.17	104.12	104.1	104.24	0	0	0	AMAN
03:00:00	0.17	0.17	0.17	104.43	104.38	104.45	0	0	0	AMAN
04:00:00	0.16	0.16	0.17	104.79	104.6	105.03	0	0	0	AMAN
05:00:00	0.16	0.16	0.17	105.06	104.88	105.32	0	0	0	AMAN
06:00:00	0.16	0.16	0.16	105.35	105.17	105.61	0	0	0	AMAN
07:00:00	0.16	0.16	0.16	105.52	105.39	105.61	0	0	0	AMAN
08:00:00	0.16	0.16	0.16	107.59	106.8	108.18	0	0	0	AMAN
09:20:00	0.16	0.16	0.17	108.92	108.1	110.01	0	0	0	AMAN
10:00:00	0.17	0.17	0.17	108.96	108.96	108.96	0	0	0	AMAN

http://sipalaga.brg.go.id