

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_140412_02 LOKASI : SUNGAI GAUNG 2

KECAMATAN: GAUNG

KABUPATEN: INDRAGIRI HILIR

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI SELASA, 26 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
09:20:03	-0.38	-0.38	-0.38	47.2	47.2	47.2	0	0	0	SIAGA
10:30:02	-0.38	-0.38	-0.38	46.7	46.7	46.7	0	0	0	SIAGA
12:40:02	-0.38	-0.38	-0.38	46.6	46.6	46.6	0	0	0	SIAGA
13:00:03	-0.38	-0.38	-0.38	46.4	46.4	46.4	0	0	0	SIAGA

http://sipalaga.brg.go.id