

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG8

LOKASI : PENYENGAT KECAMATAN : SUNGAI APIT

KABUPATEN : SIAK PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI SABTU, 16 FEBRUARI 2019

| Jam | Ground Water Level (meter) | | | Soil Moisture (%) | | | Curah Hujan (mm) | | | Ctatus |
|----------|----------------------------|-------|-------|-------------------|-------|-------|------------------|-----|-----|--------|
| | Rataan | Min | Max | Rataan | Min | Max | Komposit | Min | Max | Status |
| 00:00:00 | -0.88 | -0.88 | -0.88 | 56.85 | 56.8 | 56.9 | 0 | 0 | 0 | BAHAYA |
| 01:00:00 | -0.88 | -0.89 | -0.88 | 56.88 | 56.87 | 56.9 | 0 | 0 | 0 | BAHAYA |
| 02:00:00 | -0.88 | -0.89 | -0.88 | 56.93 | 56.9 | 56.98 | 0 | 0 | 0 | BAHAYA |
| 03:00:00 | -0.88 | -0.88 | -0.88 | 57.02 | 56.98 | 57.05 | 0 | 0 | 0 | BAHAYA |
| 04:00:00 | -0.88 | -0.88 | -0.88 | 57.15 | 57.12 | 57.19 | 0 | 0 | 0 | BAHAYA |
| 05:00:00 | -0.89 | -0.89 | -0.88 | 57.26 | 57.19 | 57.33 | 0 | 0 | 0 | BAHAYA |
| 06:10:00 | -0.89 | -0.89 | -0.89 | 57.4 | 57.33 | 57.48 | 0 | 0 | 0 | BAHAYA |
| 07:00:00 | -0.88 | -0.89 | -0.88 | 57.49 | 57.48 | 57.51 | 0 | 0 | 0 | BAHAYA |
| 08:00:00 | -0.88 | -0.89 | -0.88 | 57.61 | 57.55 | 57.69 | 0 | 0 | 0 | BAHAYA |
| 09:00:00 | -0.88 | -0.88 | -0.88 | 57.76 | 57.73 | 57.76 | 0 | 0 | 0 | BAHAYA |
| 10:00:00 | -0.88 | -0.88 | -0.88 | 57.78 | 57.76 | 57.8 | 0 | 0 | 0 | BAHAYA |
| 11:00:00 | -0.88 | -0.88 | -0.88 | 57.64 | 57.51 | 57.76 | 0 | 0 | 0 | BAHAYA |
| 12:00:00 | -0.88 | -0.88 | -0.88 | 57.4 | 57.33 | 57.48 | 0 | 0 | 0 | BAHAYA |
| 13:00:00 | -0.88 | -0.88 | -0.88 | 57.27 | 57.19 | 57.33 | 0 | 0 | 0 | BAHAYA |
| 14:00:00 | -0.88 | -0.88 | -0.88 | 57.19 | 57.19 | 57.19 | 0 | 0 | 0 | BAHAYA |

http://sipalaga.brg.go.id