

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_140412\_02 LOKASI : SUNGAI GAUNG 2

**KECAMATAN: GAUNG** 

**KABUPATEN: INDRAGIRI HILIR** 

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI SENIN, 04 MARET 2019

| Jam      | Ground Water Level (meter) |       |       | Soil Moisture (°/ <sub>o</sub> ) |      |      | Curah Hujan (mm) |     |     | Ctatus |
|----------|----------------------------|-------|-------|----------------------------------|------|------|------------------|-----|-----|--------|
|          | Rataan                     | Min   | Max   | Rataan                           | Min  | Max  | Komposit         | Min | Max | Status |
| 09:00:02 | -0.46                      | -0.47 | -0.46 | 43                               | 43   | 43   | 0                | 0   | 0   | BAHAYA |
| 10:00:01 | -0.47                      | -0.47 | -0.47 | 43.3                             | 43.3 | 43.3 | 0                | 0   | 0   | BAHAYA |
| 11:00:02 | -0.46                      | -0.46 | -0.46 | 43                               | 43   | 43   | 0                | 0   | 0   | BAHAYA |
| 12:00:01 | -0.47                      | -0.47 | -0.47 | 43                               | 43   | 43   | 0                | 0   | 0   | BAHAYA |
| 15:10:03 | -0.47                      | -0.47 | -0.47 | 43                               | 43   | 43   | 0                | 0   | 0   | BAHAYA |
| 16:40:02 | -0.47                      | -0.47 | -0.47 | 42.5                             | 42.5 | 42.5 | 0                | 0   | 0   | BAHAYA |

http://sipalaga.brg.go.id