

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_160219_02 LOKASI : AIR RUMBAI

KECAMATAN: PANGKALAN LAPAM
KABUPATEN: OGAN KOMERING ILIR
PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
01:40:00	0.35	0.35	0.35	67.7	67.7	67.7	0	0	0	AMAN
05:00:00	0.35	0.35	0.35	67.5	67.5	67.5	0	0	0	AMAN
12:20:04	0.35	0.35	0.35	67.15	67.1	67.2	0	0	0	AMAN
13:10:02	0.37	0.36	0.37	67.18	67.1	67.2	10	1	4.4	AMAN
14:00:02	0.38	0.37	0.38	67.15	67.1	67.2	0.2	0	0.2	AMAN
15:00:03	0.38	0.37	0.38	67.08	66.9	67.2	0	0	0	AMAN
16:00:01	0.38	0.37	0.38	67.13	67	67.2	0	0	0	AMAN
17:10:00	0.38	0.37	0.38	67.2	67.2	67.2	0	0	0	AMAN
18:00:01	0.38	0.38	0.38	67.15	67.1	67.2	0	0	0	AMAN
19:10:01	0.38	0.37	0.38	67.13	67.1	67.2	0	0	0	AMAN
20:00:03	0.37	0.37	0.38	67.17	67.1	67.2	0	0	0	AMAN
21:00:02	0.38	0.38	0.38	67.2	67.2	67.2	0	0	0	AMAN
22:00:03	0.38	0.37	0.38	67.15	67.1	67.2	0	0	0	AMAN
23:00:04	0.37	0.37	0.38	67.15	67.1	67.2	0	0	0	AMAN

http://sipalaga.brg.go.id