

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_621103\_04 LOKASI : BUKIT RAWI

KECAMATAN: KAHAYAN TENGAH KABUPATEN: PULANG PISAU

PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 14 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			01-1
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
01:00:01	0	0	0	71.2	71.2	71.2	0	0	0	KOSONG
02:10:10	-0.01	-0.01	-0.01	71.2	71.2	71.2	0	0	0	SIAGA
05:00:29	-0	-0	-0	70.9	70.9	70.9	0	0	0	KOSONG
06:20:12	-0	-0.01	0	71.3	71.3	71.3	0	0	0	KOSONG
07:00:07	-0.01	-0.02	0	71.3	71.3	71.3	0	0	0	SIAGA
08:00:00	-0.01	-0.04	-0	71.3	71.3	71.3	0	0	0	SIAGA
09:00:32	-0.01	-0.01	-0	71.15	71	71.3	0	0	0	SIAGA
11:40:13	-0.01	-0.01	-0.01	71.1	71.1	71.1	0	0	0	SIAGA
12:40:32	-0	-0	-0	71.2	71.2	71.2	0	0	0	KOSONG
13:20:13	-0	-0	-0	71	71	71	0	0	0	KOSONG
16:40:23	-0.01	-0.01	-0.01	70.8	70.8	70.8	0	0	0	SIAGA
17:10:07	-0	-0.01	0	70.8	70.8	70.8	0	0	0	KOSONG
18:00:51	-0.03	-0.04	-0	70.77	70.7	70.8	0	0	0	SIAGA
19:00:13	-0	-0.01	0	70.7	70.7	70.7	0	0	0	KOSONG
20:00:17	-0	-0.01	0	70.7	70.7	70.7	0	0	0	KOSONG
21:00:02	-0.01	-0.01	0	70.62	70.6	70.7	0	0	0	SIAGA
22:20:14	-0.01	-0.01	-0	70.7	70.6	70.8	0	0	0	SIAGA
23:10:06	-0	-0.01	-0	70.93	70.8	71	0	0	0	KOSONG

http://sipalaga.brg.go.id