

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : SELEH1

LOKASI: PT1-PEDAMARAN TIMUR

KECAMATAN: PEDAMARAN

KABUPATEN: OGAN KOMERING ILIR PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI MINGGU, 17 MARET 2019

| Jam | Ground Water Level (meter) | | | Soil Moisture (%) | | | Curah Hujan (mm) | | | Status |
|----------|----------------------------|-------|-------|-------------------|-------|-------|------------------|-----|-----|--------|
| | Rataan | Min | Max | Rataan | Min | Max | Komposit | Min | Max | Status |
| 00:00:00 | -4.52 | -4.52 | -4.53 | 10.05 | 10.06 | 10 | 0 | 0 | 0 | BAHAYA |
| 01:00:00 | -4.52 | -4.52 | -4.52 | 10.06 | 10.06 | 10.06 | 0 | 0 | 0 | BAHAYA |
| 02:00:00 | -4.52 | -4.52 | -4.52 | 10.06 | 10.06 | 10.06 | 0 | 0 | 0 | BAHAYA |
| 03:00:00 | -4.52 | -4.52 | -4.52 | 10.11 | 10.06 | 10.12 | 0 | 0 | 0 | BAHAYA |
| 04:00:00 | -4.52 | -4.52 | -4.52 | 10.12 | 10.12 | 10.12 | 0 | 0 | 0 | BAHAYA |
| 05:00:00 | -4.52 | -4.52 | -4.52 | 10.18 | 10.12 | 10.19 | 0 | 0 | 0 | BAHAYA |
| 06:00:00 | -4.52 | -4.52 | -4.52 | 10.13 | 10.12 | 10 | 0 | 0 | 0 | BAHAYA |
| 07:00:00 | -4.53 | -4.53 | -4.53 | 9.68 | 9.54 | 9.93 | 0 | 0 | 0 | BAHAYA |
| 08:00:00 | -4.53 | -4.53 | -4.53 | 9.4 | 9.34 | 9.47 | 0 | 0 | 0 | BAHAYA |
| 09:20:00 | -4.53 | -4.53 | -4.53 | 9.28 | 9.28 | 9.28 | 0 | 0 | 0 | BAHAYA |

http://sipalaga.brg.go.id