

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_140412_02 LOKASI : SUNGAI GAUNG 2

KECAMATAN: GAUNG

KABUPATEN: INDRAGIRI HILIR

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI JUMAT, 15 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
04:00:01	-0.58	-0.58	-0.58	38.9	38.9	38.9	0	0	0	BAHAYA
05:00:04	-0.58	-0.58	-0.58	38.6	38.6	38.6	0	0	0	BAHAYA
06:00:01	-0.59	-0.59	-0.59	38.8	38.7	38.9	0	0	0	BAHAYA
07:20:02	-0.58	-0.58	-0.58	38.7	38.7	38.7	0	0	0	BAHAYA
08:30:04	-0.59	-0.59	-0.59	38.7	38.7	38.7	0	0	0	BAHAYA

http://sipalaga.brg.go.id