

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_621103_04 LOKASI : BUKIT RAWI

KECAMATAN: KAHAYAN TENGAH KABUPATEN: PULANG PISAU

PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:10:09	-0.09	-0.09	-0.09	71.26	71.1	71.3	0	0	0	SIAGA
01:00:04	-0.09	-0.11	-0.09	71.27	71.2	71.3	0	0	0	SIAGA
02:00:07	-0.09	-0.09	-0.09	71.4	71.2	71.5	0	0	0	SIAGA
03:00:00	-0.09	-0.1	-0.09	71.4	71.4	71.4	0	0	0	SIAGA
11:30:29	-0.09	-0.09	-0.09	71.1	70.9	71.2	0	0	0	SIAGA
12:00:10	-0.09	-0.09	-0.09	70.95	70.8	71.3	0	0	0	SIAGA
13:00:04	-0.09	-0.1	-0.09	70.92	70.9	71	0	0	0	SIAGA
14:00:11	-0.09	-0.1	-0.09	70.77	70.7	70.9	0	0	0	SIAGA
15:00:02	-0.1	-0.11	-0.09	70.72	70.5	70.9	0	0	0	SIAGA
16:00:17	-0.1	-0.1	-0.09	70.55	70.5	70.6	0	0	0	SIAGA
17:00:05	-0.1	-0.1	-0.09	70.53	70.5	70.6	0	0	0	SIAGA
18:20:49	-0.1	-0.1	-0.09	70.63	70.5	70.7	0	0	0	SIAGA
19:00:54	-0.09	-0.1	-0.09	70.7	70.5	71	21	0	3.8	SIAGA
20:00:03	-0.09	-0.1	-0.09	71.24	71	71.3	41.8	0	8	SIAGA
21:20:33	-0.09	-0.1	-0.09	71.15	71	71.3	0	0	0	SIAGA
22:50:02	-0.08	-0.08	-0.08	71.3	71.3	71.3	0	0	0	SIAGA
23:10:06	-0.08	-0.08	-0.08	71.3	71.3	71.3	0.6	0	0.6	SIAGA

http://sipalaga.brg.go.id