

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_147205_01 LOKASI : PELINTUNG

KECAMATAN: MEDANG KAMPAI

KABUPATEN : DUMAI PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

| Jam | Ground Water Level (meter) | | | Soil Moisture (%) | | | Curah Hujan (mm) | | | 01-1 |
|----------|----------------------------|-------|-------|-------------------|------|------|------------------|-----|-----|--------|
| | Rataan | Min | Max | Rataan | Min | Max | Komposit | Min | Max | Status |
| 00:00:00 | -0.87 | -0.87 | -0.86 | 18.2 | 18.2 | 18.2 | 0 | 0 | 0 | BAHAYA |
| 01:10:01 | -0.86 | -0.87 | -0.86 | 18.2 | 18.2 | 18.2 | 0 | 0 | 0 | BAHAYA |
| 02:00:04 | -0.87 | -0.87 | -0.87 | 18.2 | 18.2 | 18.2 | 0 | 0 | 0 | BAHAYA |
| 03:00:00 | -0.86 | -0.87 | -0.86 | 18.2 | 18.2 | 18.2 | 0 | 0 | 0 | BAHAYA |
| 11:30:01 | -0.87 | -0.87 | -0.87 | 18.03 | 18 | 18.1 | 0 | 0 | 0 | BAHAYA |
| 12:10:01 | -0.87 | -0.88 | -0.87 | 17.98 | 17.9 | 18 | 0 | 0 | 0 | BAHAYA |
| 13:00:01 | -0.87 | -0.87 | -0.87 | 18 | 18 | 18 | 0 | 0 | 0 | BAHAYA |
| 14:00:02 | -0.88 | -0.88 | -0.88 | 17.9 | 17.5 | 18.1 | 0 | 0 | 0 | BAHAYA |
| 15:00:03 | -0.88 | -0.88 | -0.87 | 18 | 18 | 18 | 0 | 0 | 0 | BAHAYA |
| 16:00:02 | -0.88 | -0.88 | -0.87 | 18 | 18 | 18 | 0 | 0 | 0 | BAHAYA |
| 17:00:03 | -0.88 | -0.88 | -0.87 | 17.9 | 17.9 | 17.9 | 0 | 0 | 0 | BAHAYA |
| 18:10:02 | -0.87 | -0.87 | -0.87 | 17.95 | 17.9 | 18 | 0 | 0 | 0 | BAHAYA |
| 19:10:00 | -0.87 | -0.87 | -0.87 | 18 | 18 | 18 | 0 | 0 | 0 | BAHAYA |
| 20:00:02 | -0.87 | -0.87 | -0.87 | 18 | 18 | 18 | 0 | 0 | 0 | ВАНАҮА |
| 21:00:03 | -0.88 | -0.9 | -0.87 | 18 | 18 | 18 | 0 | 0 | 0 | ВАНАҮА |
| 22:00:01 | -0.87 | -0.87 | -0.87 | 18 | 18 | 18 | 0 | 0 | 0 | ВАНАҮА |
| 23:00:01 | -0.87 | -0.87 | -0.87 | 18 | 18 | 18 | 0 | 0 | 0 | ВАНАҮА |

http://sipalaga.brg.go.id