

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG10 LOKASI : DOMPAS KECAMATAN : BUKIT BATU KABUPATEN : BENGKALIS

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI MINGGU, 24 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	-1.42	-1.42	-1.42	36.59	36.04	37.21	0	0	0	BAHAYA
01:00:00	-1.42	-1.42	-1.42	39.33	37.27	41.22	0	0	0	BAHAYA
02:00:00	-1.42	-1.42	-1.42	42.59	41.9	43.64	0	0	0	BAHAYA
03:00:00	-1.42	-1.42	-1.42	43.67	43.28	44.13	0	0	0	BAHAYA
04:00:00	-1.42	-1.42	-1.42	42.79	42.59	43.18	0	0	0	BAHAYA
05:00:00	-1.42	-1.42	-1.42	43.49	43.34	43.64	0	0	0	BAHAYA
06:00:00	-1.42	-1.42	-1.42	43.57	43.54	43.67	0	0	0	BAHAYA
07:00:00	-1.42	-1.42	-1.42	43.67	43.48	43.87	0	0	0	ВАНАҮА
08:00:00	-1.42	-1.42	-1.42	43.71	43.28	44.04	0	0	0	BAHAYA
09:00:00	-1.42	-1.42	-1.42	43.46	43.21	43.71	0	0	0	BAHAYA
10:00:00	-1.42	-1.42	-1.42	43.28	42.88	43.51	0	0	0	BAHAYA
11:00:00	-1.42	-1.42	-1.42	42.53	42.36	42.72	0	0	0	ВАНАҮА
12:00:00	-1.42	-1.42	-1.42	41.03	38.89	42.46	0	0	0	ВАНАҮА
13:00:00	-1.42	-1.42	-1.42	41.3	40.44	42.03	0	0	0	ВАНАҮА
14:00:00	-1.42	-1.42	-1.42	41.84	41.71	41.9	0	0	0	ВАНАҮА
15:00:00	-1.42	-1.42	-1.42	41.59	41.42	41.74	0	0	0	ВАНАҮА

http://sipalaga.brg.go.id