

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG2

LOKASI : PULAI GADING
KECAMATAN : BAYUNG LENCIR
KABUPATEN : MUSI BANYUASIN
PROVINSI : SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI JUMAT, 01 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.17	0.18	0.18	100.03	100.04	99.98	0	0	0	AMAN
01:00:00	0.17	0.18	0.18	100.2	100.1	100.3	0	0	0	AMAN
02:00:00	0.18	0.18	0.19	100.35	100.3	100.43	0	0	0	AMAN
03:00:00	0.18	0.18	0.19	101.53	100.36	102.77	0	0	0	AMAN
04:00:00	0.17	0.18	0.18	102.99	102.84	103.11	0	0	0	AMAN
05:00:00	0.17	0.18	0.18	103.25	103.11	103.32	0	0	0	AMAN
06:00:00	0.17	0.18	0.18	103.32	103.32	103.32	0	0	0	AMAN
07:00:00	0.17	0.17	0.18	103.32	103.32	103.32	0	0	0	AMAN
08:00:00	0.17	0.17	0.18	103.32	103.32	103.32	0	0	0	AMAN
09:00:00	0.17	0.18	0.18	103.22	103.05	103.32	0	0	0	AMAN
10:00:00	0.17	0.18	0.18	102.62	102.22	103.05	0.5	0	0.5	AMAN
11:00:00	0.18	0.18	0.18	102.02	102.02	102.02	2.5	2.5	2.5	AMAN

http://sipalaga.brg.go.id