

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_611203_02 LOKASI : SIMPANG KANAN 2 KECAMATAN : SUNGAI AMBAWANG

KABUPATEN: KUBU RAYA

PROVINSI: KALIMANTAN BARAT

DATA TABEL: JAM-JAMAN PADA HARI SELASA, 19 FEBRUARI 2019

| Jam | Ground Water Level (meter) | | | Soil Moisture (°/ _o) | | | Curah Hujan (mm) | | | Otatus |
|----------|----------------------------|-------|-------|----------------------------------|-----|-----|------------------|-----|-----|--------|
| | Rataan | Min | Max | Rataan | Min | Max | Komposit | Min | Max | Status |
| 00:40:13 | -0.52 | -0.52 | -0.52 | 8.3 | 8.3 | 8.3 | 0 | 0 | 0 | BAHAYA |
| 02:30:06 | -0.52 | -0.52 | -0.52 | 8.3 | 8.3 | 8.3 | 0 | 0 | 0 | BAHAYA |
| 03:00:01 | -0.52 | -0.52 | -0.52 | 8.27 | 8 | 8.5 | 0 | 0 | 0 | BAHAYA |
| 04:00:02 | -0.52 | -0.52 | -0.51 | 8.28 | 8 | 8.5 | 0 | 0 | 0 | BAHAYA |
| 05:00:07 | -0.52 | -0.52 | -0.52 | 7.9 | 7.8 | 8.3 | 0 | 0 | 0 | BAHAYA |
| 06:20:14 | -0.53 | -0.55 | -0.52 | 8 | 8 | 8 | 0 | 0 | 0 | BAHAYA |
| 07:10:39 | -0.52 | -0.52 | -0.52 | 8 | 8 | 8 | 0 | 0 | 0 | BAHAYA |
| 08:20:38 | -0.52 | -0.52 | -0.52 | 8.3 | 8.3 | 8.3 | 0 | 0 | 0 | BAHAYA |
| 09:20:20 | -0.52 | -0.52 | -0.52 | 8.17 | 8 | 8.5 | 0 | 0 | 0 | BAHAYA |
| 10:50:22 | -0.52 | -0.52 | -0.52 | 7.6 | 7.6 | 7.6 | 0 | 0 | 0 | BAHAYA |
| 11:00:23 | -0.52 | -0.52 | -0.52 | 7.48 | 7.1 | 7.9 | 0 | 0 | 0 | BAHAYA |
| 12:00:16 | -0.51 | -0.52 | -0.51 | 7.25 | 7 | 7.4 | 0 | 0 | 0 | BAHAYA |
| 13:00:29 | -0.51 | -0.51 | -0.51 | 6.95 | 6.8 | 7.1 | 0 | 0 | 0 | BAHAYA |
| 14:30:29 | -0.51 | -0.51 | -0.51 | 6.3 | 6.3 | 6.3 | 0 | 0 | 0 | BAHAYA |
| 16:40:41 | -0.51 | -0.51 | -0.51 | 6.9 | 6.9 | 6.9 | 0 | 0 | 0 | BAHAYA |
| 17:20:13 | -0.51 | -0.51 | -0.51 | 6.8 | 6.7 | 6.9 | 0 | 0 | 0 | BAHAYA |
| 18:20:05 | -0.51 | -0.51 | -0.51 | 6.55 | 6.4 | 6.7 | 0 | 0 | 0 | BAHAYA |
| 19:00:20 | -0.51 | -0.51 | -0.51 | 6.87 | 6.7 | 7 | 0 | 0 | 0 | BAHAYA |
| 20:00:07 | -0.52 | -0.52 | -0.52 | 6.9 | 6.9 | 6.9 | 0 | 0 | 0 | BAHAYA |

http://sipalaga.brg.go.id