

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_140412\_02 LOKASI : SUNGAI GAUNG 2

**KECAMATAN: GAUNG** 

**KABUPATEN: INDRAGIRI HILIR** 

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI SABTU, 16 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
07:40:01	-0.6	-0.6	-0.6	36.6	36.6	36.6	0	0	0	BAHAYA
14:50:02	-0.6	-0.6	-0.6	36.7	36.7	36.7	0	0	0	BAHAYA
15:10:02	-0.61	-0.61	-0.61	36.4	36.4	36.4	0	0	0	BAHAYA
17:10:02	-0.6	-0.6	-0.6	36.1	36.1	36.1	0	0	0	BAHAYA
21:50:03	-0.6	-0.6	-0.6	35.7	35.7	35.7	0	0	0	BAHAYA
22:20:01	-0.61	-0.61	-0.6	35.65	35.5	35.8	0	0	0	BAHAYA
23:00:03	-0.61	-0.61	-0.6	35.8	35.8	35.8	0	0	0	BAHAYA

http://sipalaga.brg.go.id