

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : KECIL1

LOKASI : PM-PADURAN MULYA KECAMATAN : SEBANGAU KUALA KABUPATEN : PULANG PISAU

PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI MINGGU, 03 MARET 2019

| Jam | Ground Water Level (meter) | | | Soil Moisture (%) | | | Curah Hujan (mm) | | | Ctatus |
|----------|----------------------------|-------|-------|-------------------|-------|-------|------------------|-----|-----|--------|
| | Rataan | Min | Max | Rataan | Min | Max | Komposit | Min | Max | Status |
| 00:00:00 | -2.93 | -2.93 | -2.93 | 74.47 | 74.38 | 74.54 | 0 | 0 | 0 | BAHAYA |
| 01:00:00 | -2.92 | -2.92 | -2.93 | 74.86 | 74.54 | 75.49 | 0 | 0 | 0 | BAHAYA |
| 02:00:00 | -2.92 | -2.92 | -2.92 | 75.01 | 74.82 | 75.17 | 0 | 0 | 0 | BAHAYA |
| 03:00:00 | -2.92 | -2.92 | -2.92 | 75.02 | 74.58 | 75.33 | 0 | 0 | 0 | BAHAYA |
| 04:00:00 | -2.92 | -2.92 | -2.93 | 74.51 | 74.3 | 74.9 | 0 | 0 | 0 | BAHAYA |
| 05:00:00 | -2.93 | -2.92 | -2.93 | 74.24 | 73.91 | 74.54 | 0 | 0 | 0 | BAHAYA |
| 06:00:00 | -2.93 | -2.93 | -2.94 | 73.85 | 73.59 | 74.26 | 0 | 0 | 0 | ВАНАҮА |
| 07:00:00 | -2.95 | -2.94 | -2.99 | 72.87 | 71.96 | 73.28 | 0 | 0 | 0 | ВАНАҮА |
| 08:00:00 | -3 | -2.99 | -3 | 75.01 | 72.15 | 77.51 | 0 | 0 | 0 | ВАНАҮА |
| 09:00:00 | -3.01 | -3 | -3.01 | 76.83 | 76.62 | 77.06 | 0 | 0 | 0 | ВАНАҮА |
| 10:00:00 | -3.01 | -3 | -3.01 | 77 | 76.78 | 77.43 | 0 | 0 | 0 | BAHAYA |
| 11:00:00 | -2.99 | -2.97 | -3 | 72.32 | 71.38 | 73.87 | 11 | 0 | 6.5 | ВАНАҮА |
| 12:00:00 | -2.99 | -2.97 | -3 | 71.5 | 71.23 | 72.31 | 1 | 0 | 1 | ВАНАҮА |
| 13:00:00 | -2.97 | -2.96 | -3 | 72.37 | 70.88 | 73.28 | 3 | 0 | 2 | ВАНАҮА |
| 14:00:00 | -2.95 | -2.95 | -2.96 | 73.22 | 73.01 | 73.36 | 0.5 | 0 | 0.5 | ВАНАҮА |
| 15:00:00 | -2.95 | -2.95 | -2.95 | 73.44 | 73.44 | 73.44 | 0 | 0 | 0 | ВАНАҮА |

http://sipalaga.brg.go.id