

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_140810_01

LOKASI : SAM SAM
KECAMATAN : KANDIS
KABUPATEN : SIAK
PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatua
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:02	-0.55	-0.56	-0.55	24.85	24.8	24.9	0	0	0	BAHAYA
01:00:02	-0.55	-0.56	-0.55	24.77	24.7	24.8	0	0	0	BAHAYA
02:00:07	-0.56	-0.56	-0.56	24.7	24.7	24.7	0	0	0	BAHAYA
03:00:01	-0.56	-0.56	-0.56	24.7	24.7	24.7	0	0	0	BAHAYA
05:00:01	-0.56	-0.56	-0.56	24.7	24.7	24.7	0	0	0	BAHAYA
11:30:03	-0.56	-0.56	-0.56	24.6	24.5	24.7	0	0	0	BAHAYA
12:00:05	-0.56	-0.57	-0.56	24.73	24.7	24.9	0	0	0	BAHAYA
13:00:07	-0.56	-0.58	-0.56	24.7	24.4	24.8	0	0	0	BAHAYA
14:00:00	-0.56	-0.56	-0.56	24.5	24.5	24.5	0	0	0	BAHAYA
15:00:00	-0.56	-0.56	-0.56	33.46	24.5	68.9	1.4	0	1.4	BAHAYA
16:10:00	-0.56	-0.57	-0.56	41.64	38.8	45.5	0	0	0	BAHAYA
17:00:01	-0.56	-0.57	-0.56	36.04	33.9	38	0	0	0	BAHAYA
18:00:03	-0.56	-0.57	-0.56	32.08	31	33.4	0	0	0	BAHAYA
19:00:00	-0.56	-0.57	-0.56	30.03	29.6	30.5	0	0	0	BAHAYA
20:00:03	-0.56	-0.57	-0.56	29.18	28.8	29.4	0	0	0	BAHAYA
21:00:14	-0.56	-0.58	-0.56	28.7	28.6	28.8	0	0	0	BAHAYA
22:00:07	-0.56	-0.57	-0.56	28.4	28.3	28.6	0	0	0	BAHAYA
23:00:02	-0.56	-0.56	-0.56	28.3	28.3	28.3	0	0	0	BAHAYA

http://sipalaga.brg.go.id