

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN: BRG_160224_01 LOKASI: CINTA JAYA 1 KECAMATAN: PEDAMARAN

KABUPATEN: OGAN KOMERING ILIR PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SENIN, 11 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			01.1
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:20:03	-0.43	-0.43	-0.43	11	11	11	0	0	0	ВАНАҮА
01:00:39	-0.43	-0.43	-0.42	10.85	10.8	11	0	0	0	ВАНАҮА
02:10:01	-0.43	-0.43	-0.42	10.9	10.9	10.9	0	0	0	ВАНАҮА
03:00:05	-0.43	-0.43	-0.43	10.9	10.9	10.9	0	0	0	ВАНАҮА
04:00:09	-0.43	-0.44	-0.42	10.88	10.8	10.9	0	0	0	BAHAYA
05:00:00	-0.43	-0.43	-0.43	10.8	10.8	10.8	0	0	0	BAHAYA
06:00:05	-0.43	-0.43	-0.43	10.75	10.7	10.8	0	0	0	ВАНАҮА
07:00:06	-0.43	-0.44	-0.43	10.72	10.7	10.8	0	0	0	ВАНАҮА
08:00:20	-0.43	-0.44	-0.43	10.7	10.7	10.7	0	0	0	BAHAYA
09:10:55	-0.43	-0.44	-0.43	10.64	10.5	10.8	0	0	0	BAHAYA
10:00:22	-0.44	-0.44	-0.44	10.8	10.8	10.8	0	0	0	BAHAYA
11:00:16	-0.44	-0.46	-0.43	10.65	10.5	10.8	0	0	0	ВАНАҮА
12:30:13	-0.43	-0.43	-0.43	10.65	10.5	10.8	0	0	0	BAHAYA
13:00:01	-0.43	-0.44	-0.43	10.7	10.6	10.8	0	0	0	BAHAYA
14:00:13	-0.44	-0.44	-0.43	10.63	10.6	10.7	0	0	0	BAHAYA
16:10:17	-0.44	-0.46	-0.43	10.6	10.6	10.6	0	0	0	ВАНАҮА
17:00:17	-0.44	-0.44	-0.44	10.47	10.4	10.6	0	0	0	ВАНАҮА
18:10:33	-0.44	-0.45	-0.43	10.45	10.4	10.6	0	0	0	ВАНАҮА
19:20:33	-0.44	-0.44	-0.44	10.5	10.5	10.5	0	0	0	BAHAYA
20:00:14	-0.45	-0.47	-0.44	10.4	10.2	10.5	0	0	0	BAHAYA
21:00:13	-0.44	-0.45	-0.44	10.22	10.2	10.3	0	0	0	ВАНАҮА
22:00:17	-0.45	-0.45	-0.44	10.3	10.3	10.3	0	0	0	BAHAYA
23:20:20	-0.45	-0.45	-0.45	10.3	10.3	10.3	0	0	0	ВАНАҮА

http://sipalaga.brg.go.id