

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_140412_02 LOKASI : SUNGAI GAUNG 2

KECAMATAN: GAUNG

KABUPATEN: INDRAGIRI HILIR

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI RABU, 20 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
10:20:01	-0.16	-0.16	-0.16	56.2	56.2	56.2	0.4	0.4	0.4	SIAGA
16:10:00	-0.19	-0.19	-0.19	50.3	50.3	50.3	0.8	0.8	0.8	SIAGA
18:30:03	-0.18	-0.18	-0.18	51.3	51.3	51.3	0	0	0	SIAGA
19:00:03	-0.19	-0.19	-0.18	51.1	50.9	51.4	0.4	0	0.2	SIAGA

http://sipalaga.brg.go.id