

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : OKI2

LOKASI : SIMPANG TIGA
KECAMATAN : TULUNG SELAPAN
KABUPATEN : OGAN KOMERING ILIR
PROVINSI : SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SELASA, 26 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.05	0.04	0.05	10.47	11.32	8.48	0	0	0	AMAN
01:00:00	-0	-0.01	0.01	9.71	10.06	9.93	0	0	0	KOSONG
02:00:00	0.01	0	0.01	10.27	10.12	10	0	0	0	AMAN
03:00:00	0.02	0.02	0.02	10.46	10.76	9.47	0	0	0	AMAN
04:00:00	0.02	0.02	0.02	10.88	10.82	9.34	0	0	0	AMAN
05:00:00	0.02	0.02	0.02	10.57	11.01	9.74	0	0	0	AMAN
06:00:00	0.02	0.02	0.02	10.78	10.19	9.21	0	0	0	AMAN
07:00:00	0.02	0.02	0.02	9.64	10.12	9.21	0	0	0	AMAN
08:00:00	0.02	0.02	0.02	10.14	10.38	10	0	0	0	AMAN
09:00:00	0.03	0.02	0.03	10.6	10.06	11.57	0	0	0	AMAN
10:00:00	0.04	0.03	0.04	10.18	10.7	9.74	0	0	0	AMAN
11:00:00	0.05	0.04	0.05	10.08	10.25	9.93	0.5	0	0.5	AMAN
12:00:00	0.05	0.05	0.05	10.2	10.19	8.68	0	0	0	AMAN
13:00:00	0.05	0.05	0.06	10.33	10.51	9.93	0	0	0	AMAN
14:00:00	0.06	0.06	0.06	10.57	10.57	10.57	0	0	0	AMAN

http://sipalaga.brg.go.id