

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_627104\_02 LOKASI : TN SEBANGAU 2

**KECAMATAN: SABANGAU** 

KABUPATEN: KOTA PALANGKARAYA PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI MINGGU, 10 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
03:40:00	0.59	0.59	0.59	77.3	77.3	77.3	0	0	0	AMAN
04:40:00	0.58	0.58	0.58	77.3	77.3	77.3	0	0	0	AMAN
05:30:01	0.58	0.58	0.59	77.25	77.2	77.3	0	0	0	AMAN
06:00:00	0.58	0.58	0.58	77.2	77.2	77.2	0	0	0	AMAN
07:50:03	0.58	0.58	0.58	77.9	77.9	77.9	0	0	0	AMAN
08:10:00	0.57	0.57	0.58	77.67	77.5	77.8	0	0	0	AMAN
09:30:03	0.57	0.57	0.57	77.6	77.6	77.6	0	0	0	AMAN
10:00:01	0.57	0.57	0.57	77.85	77.7	78	0	0	0	AMAN
11:10:00	0.57	0.57	0.57	78.05	77.9	78.2	0	0	0	AMAN
13:50:01	0.56	0.56	0.56	78.6	78.6	78.6	0	0	0	AMAN
14:00:00	0.56	0.56	0.56	78.6	78.6	78.6	0	0	0	AMAN
15:30:00	0.56	0.56	0.56	77.6	77.6	77.6	0	0	0	AMAN
17:40:00	0.55	0.55	0.55	78	78	78	0	0	0	AMAN
22:20:01	0.54	0.54	0.54	77.75	77.7	77.8	0	0	0	AMAN

http://sipalaga.brg.go.id